

A close-up photograph of the drainage system of an air conditioning unit. The unit is mounted on a wall, and the underside is covered with silver insulation. Three white PVC pipes are visible, each with a purple cap. A grey corrugated pipe is also present. Labels A, B, and C are overlaid on the image to identify the different components.

A - Tuyau de drain vers la pressure switch

B - Tuyau de drainage vers le drain commun

C - Pan de récupération de l'eau de l'air climatisé